

MEDIA AND OPERATING CONDITIONS: The sulfur content in the fuel gas was 50 – 200 ppm. Coil has been in service for 46 years.

TIME TO DETERIORATION : near HAZ: since last Turn around. Others: over years



CORROSION IN REFINERY INDUSTRY FAILURE ATLAS

CASE HISTORY n° 3

ANSWER

TYPE OF CORROSION : a. creep **b.** cracks related to welding new and 46 years old tubing together.

API 571 CLASSIFICATION: a. 4.2.8 b. ? (4.2.12)

CAUSES :

- **a.** Ageing of tubes, which was not expected to be in the creep range according to API 530 and API 581. Inspection for creep has never been done.
- Problems welding 46 years old stainless steel together with new stainless steel. Cracks were not
 Found in the control of the welds (dye penetrant and radiographic film).

REMEDY:

a. Retubing to similar material (SS 304). SS 347 or 321recommended, but not available at the time of delivery.

b. Future recommendations: Additional control of welds after welding old tubing together with new material. This with Ultrasonic measurements with 45% angled probe to detect eventually cracks on the inner side of the welds.

PUBLICATION - TECHNICAL REPORT: -

BIBLIOGRAPHIC REFERENCES :

API 581 API 530 API 571